	Title	Revision	Date	Page			
	Measuring PQ Issues in a Bus Depot Using Unipower HW and Software				R3	20-Feb-2025	1(4)
	Туре	Signature	Checked	File	I		
	Case Study	то	PSA	Case Study, Electrical bus depot in Sweden			

Introduction

This case study explores how advanced power quality measurement technology facilitated the diagnosis of severe power quality disturbances in a bus depot. These disturbances, which neither the bus operator nor the bus manufacturer initially attributed to electrical quality issues, were ultimately traced to deficiencies in the depot's charging infrastructure.

Background

A bus depot, integrating both AC and DC charging infrastructure, was experiencing operational disruptions. The facility contained AC chargers (22 kW) designated for minibuses and DC fast chargers (200 kW) for larger electric buses. Depot operators observed that the AC chargers were intermittently failing when the DC chargers where in use. These issues impacted vehicle availability and overall operational efficiency. The root cause of these disruptions remained undetermined until an extensive power quality analysis was conducted.



Figure 1: Aireal view of the bus depot. Large buses are DC charged; minibuses are AC charged (overnight charging)

Diagnostic Assessment

A power quality investigation revealed that the power disturbances originated from the absence of necessary electrical filters in the DC chargers. Without these filters, the operation of DC chargers induced significant harmonic distortions in the local voltage, interfering with the stability of the AC charging units.

	Title Moncuring DO Issues in a Pr	Revision	Date	Page				
	Measuring PQ Issues in a Bus Depot Using Unipower HW and Software					20-Feb-2025	2(4)	
	Туре	Signature	Checked	File				
	Case Study	то	PSA	Case Study, Electrical bus depot in Sweden				

Power Quality Analysis

The measurement data indicated that the Swedish power quality standard (EIFS) had been exceeded due to harmonic content in the 7th and 11th harmonic. EIFS is a local adaption of the European EN50160 norm.

5 Individual harmonic analysis

The individual harmonic analysis is assessed according to EIFS 2023:3 section 7.4-7.6. All 10m values for each individual harmonic voltage must be less than or equal to the limit values in the table.

пап	Harmonic no: limit in % of fundamental									
#	Limit [%]	MaxU1 [%]	95% U1 [%]	MaxU2 [%]	95% U2 [%]	MaxU3 [%]	95% U3 [%]	Result		
2	2	0,10	0,03	0,07	0,02	0,09	0,03	Passed		
3	5	0,48	0,29	0,57	0,45	0,57	0,37	Passed		
4	1	0,12	0,02	0,06	0,02	0,04	0,02	Passed		
5	6	3,63	1,92	3,69	1,99	3,65	1,91	Passed		
6	0,5	0,11	0,02	0,05	0,02	0,05	0,02	Passed		
7	5	4,79	4,14	5,19	4,28	5,32	4,32	Failed		
8	0,5	0,06	0,02	0,06	0,02	0,05	0,02	Passed		
9	1,5	0,61	0,34	1,16	0,67	1,00	0,65	Passed		
10	0,5	0,10	0,02	0,11	0,02	0,10	0,02	Passed		
11	3,5	4,23	3,53	4,10	3,61	3,83	3,36	Failed		
12	0,5	0,04	0,02	0,03	0,01	0,04	0,02	Passed		
13	3	1,81	1,27	1,87	1,34	2,00	1,34	Passed		
14	0,5	0,05	0,01	0,03	0,01	0,04	0,01	Passed		
15	1	0,91	0,65	0,73	0,53	0,78	0,61	Passed		
16	0,5	0,03	0,01	0,03	0,01	0,02	0,01	Passed		
17	2	1,74	1,26	1,73	1,23	1,64	1,25	Passed		
18	0,5	0,02	0,01	0,01	0,01	0,02	0,01	Passed		
19	1,5	1,32	0,84	1,32	0,81	1,38	0,77	Passed		
20	0,5	0,02	0,00	0,02	0,00	0,02	0,00	Passed		
21	0,75	0,61	0,40	0,57	0,34	0,57	0,28	Passed		
22	0,5	0,02	0,00	0,01	0,00	0,02	0,00	Passed		
23	1,5	0,88	0,47	0,85	0,44	0,84	0,40	Passed		
24	0,5	0,02	0,00	0,01	0,00	0,01	0,00	Passed		
25	1,5	0,00	0,00	0,00	0,00	0,00	0,00	Passed		

Harmonic no: limit in % of fundamental

Figure 2: 7th and 11th Harmonic are failing

Additionally, the analysis revealed that the power factor was significantly below optimal levels, causing energy inefficiencies within the depot's electrical distribution system.

Implementation of Mitigation Measures

Following the identification of these power quality issues, the DC charger manufacturer installed appropriate electrical filtering solutions. A subsequent measurement campaign was conducted to assess the effectiveness of these interventions. The results demonstrated a significant improvement:


• **Substantial reduction in harmonic distortions**, bringing them within regulatory compliance limits.



Mon 22 Thu 1 Thu 8 Thu 15 Thu 22 Fri 1 Time Fri 8 Fri 15 Fri 22 Mon 1 Mon 8 2024 Jan Unipower PQSecure

0-

Figure 3: THD before and after filters were installed



Power factor improvement from 88% to 97%, enhancing overall energy efficiency by 9%.

Figure 4: Power factor before and after filters were installed

Title					Date	Page
Measuring PQ Issues in a Bus Depot Using Unipower HW and Software				R3	20-Feb-2025	4(4)
Туре	Signature	Checked	File			
Case Study	то	PSA	Case Study, Electrical bus depot in Sweden			

Lessons Learned & Next Steps

- **Implement continuous monitoring:** Regularly measure power factor, harmonic distortion, and other vital parameters to detect potential issues before they escalate.
- **Evaluate expansion opportunities:** As the electric fleet grows, continuously assess whether the existing filters, chargers, and electrical network remain adequate.
- **Strengthen collaboration with manufacturers:** Ongoing dialogue with both bus and charger suppliers helps ensure that proper filters and components are in place from the outset.
- Analyze economic implications: Beyond energy savings, conduct a return-on-investment (ROI) analysis of the filter installation and the improvements in system stability.
- **Educate relevant staff:** Ensure that electrical technicians and depot managers understand fundamental power quality principles, enabling rapid response to emerging anomalies.

This case study underscores the critical role of advanced power quality diagnostics in identifying and resolving electrical disturbances. By systematically analyzing power parameters and implementing targeted mitigation strategies, significant improvements in charging infrastructure reliability and energy efficiency were realized. The findings highlight the necessity of continuous power quality assessments for ensuring optimal performance and compliance in electric bus depots.